

## Exam – Rotating Equipment Safety Overview

### True (T) or False (F)

1. **T** F Entanglement occurs when a body part is drawn into the rotating part of a machine or tool.
2. **T** F Entanglement injuries can be prevented by ensuring that all required machine and tool guards are in-place.
3. **T** F Long hair should be tied back or secured under a hat or hard-hat to prevent entanglement.
4. T **F** Jewelry does not pose an entanglement hazard.
5. **T** F Rotating equipment posing entanglement hazards include drills, saws and milling machines.
6. T **F** It is OK to operate a piece of equipment with a missing guard.
7. **T** F E-stops should be readily available for machines.
8. **T** F Entanglement injuries are preventable.

### (Select the best answer)

9. Which of the following pose entanglement hazards?
  - A. Long hair
  - B. Loose clothing
  - C. Jewelry
  - D. All of the above**
10. Entanglement can cause which of the following injuries?
  - A. Fractures
  - B. Amputations
  - C. Scalping
  - D. All of the above**